

Fire Alarm Inspection Certificate APRIL 2024

This certificate confirms that we have completed the maintenance service of your fire alarm system and certify that the said work for which we have been responsible complies to the best of our knowledge and belief with the recommendations of clause 45 of British Standard BS 5839-1:2017 (inspection and test over a 12-month period), except for the variations, if any, stated on this certificate.

The extent of liability of the signatory is limited to the system as described below.

The user should arrange for corrective action where necessary.

Registered business		Site address (if applicable)		Customer address	
Firecheck North West Limited Firecheck House 9 Avon Road Culcheth Warrington Cheshire WA3 5DT				Croft Village Hall 5 Mustard Lane Croft Warrington Cheshire WA3 7DG	
Fire Alarm					
			Result		
Location	Type/Size	ID No.	PASS	FAIL	Comments
Main Entrance	Call Point	1	PASS		
Main Entrance	Sounder Beacon	2	PASS		
Main Entrance	Smoke Detector	3	PASS		
Ladies Toilets	Beacon	4	PASS		
Gents Toilets	Beacon	5	PASS		
Cellar	Smoke Detector	6	PASS		
Bar	Smoke Detector	7	PASS		
Main Hall	Call Point	8	PASS		
Main Hall	Call Point	9	PASS		
Main Hall	Smoke Detector	10	PASS		
Main Hall	Smoke Detector	11	PASS		
Main Hall	Smoke Detector	12	PASS		
Main Hall	Sounder Beacon	13	PASS		
Main Hall	Sounder Beacon	14	PASS		

Stage	Smoke Detector	15	PASS		
Store Room	Smoke Detector	16	PASS		
Kitchen	Call Point	17	PASS		
Kitchen	Heat Detector	18	PASS		
Electric Room	Smoke Detector	19	PASS		
Birch Hall WC Corridor	Call Point	20	PASS		
Birch Hall WC Corridor	Smoke Detector	21	PASS		
Birch Hall WC Corridor	Sounder Beacon	22	PASS		
Disabled WC	Beacon	23	PASS		
Gents WC	Beacon	24	PASS		
Ladies WC	Beacon	25	PASS		
Birch Hall Kitchen	Heat Detector	26	PASS		
Kitchen Exit	Call Point	27	PASS		
Kitchen Exit	Smoke Detector	28	PASS		
Birch Hall	Call Point	29	PASS		
Birch Hall	Smoke Detector	30	PASS		
Birch Hall	Smoke Detector	31	PASS		
Birch Hall	Sounder Beacon	32	PASS		
Birch Hall Store Room WC Area	Smoke Detector	33			NO ACCESS
Rear Boiler Cupboard	Heat Detector	34	PASS		
Rear Boiler Cupboard	Call Point	35	PASS		
Front Boiler Cupboard	Heat Detector	36	PASS		
Front Boiler Cupboard	Call Point	37	PASS		
37					

Engineer Name: Mike Schofield	Name:	Date: April 2024 Next Annual Service: APRIL 2025